Linear Unit QME

Q	ME20 -	2x360 ·	- 1194 -	BWILM	- SR/SL160	5 - Z
Product type QME12 = ø12 shaft + linear ball bearing LME12UU QME20 = ø20 shaft + linear ball bearing SBE20UU QME30 = ø30 shaft + linear ball bearing SBE30UU						
Absolute stroke Stroke between mechanical stops (mm) Prefix "2x" means 2 moving parts with left+right -hand drive screw						
Ltot Length distance between mounting holes (mm)						
Options B = with bellows W = with hand wheel WL = hand wheel and locking device on drive screw WIL = hand wheel, locking device and position indicator M = with magnet and rail for end/position switches (switches order	red separa	ately)				
Screw type(1) SR082,5 Ball screw lead 2,5 mm for QME12 TR1203 Tr screw lead 3 mm for QME12 TL1203 Left hand Tr screw lead 3 mm for QME12 SR1605 Ball screw lead 5 mm for QME20 TR1604 Tr screw lead 4 mm for QME20 TL1604 Left hand Tr screw lead 4 mm for QME20 SR3205 Ball screw lead 5 mm for QME30 SL3205 Left hand ball screw lead 5 mm for QME30 SR3210 Ball screw lead 10 mm for QME30 SR3220 Ball screw lead 20 mm for QME30 TR3006 Tr screw lead 6 mm for QME30						
Customisation Z = according to custom drawing/specification						

⁽¹⁾ In case of left+right unit, screws of same lead and type must be selected, for example TR1203 and TL1203.